

AD-A144 201


NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
BRISTOL FISH AND GAME (U) CORPS OF ENGINEERS WALTHAM
MA NEW ENGLAND DIV APR 81


1/1

UNCLASSIFIED

F/G 13/13

NL





AD-A144 201

BASIN
TOWN OF



BRISTOL FISH AND GAME CLUB DAM
CT-00299

1981

DTIC FILE COPY

DTIC
ELECTE
S AUG 13 1984 D
D

NATIONAL DAM INSPECTION PROGRAM
CORPS OF ENGINEERS

DISTRIBUTION
Approved for public
Distribution Unlimited

84 08 09 083

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER CT 00299	2. GOVT ACCESSION NO. AD-A144201	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Bristol Fish and Game Club Dam NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS		8. CONTRACT OR GRANT NUMBER(s)
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE April 1981
		13. NUMBER OF PAGES 45
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		16a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Quinnipiac River Basin Town of Wolcott		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) Bristol Fish and Game Club Dam is located on Cussgutter Brook in a rural area. The dam is an earth embankment founded on bedrock and measuring approximately 600 feet long, 22.5 ft. high and 12 feet wide at the top. Based on the visual inspection the project is assessed as being in good condition.		

LOW HAZARD



PHASE I INSPECTION REPORT
NATIONAL PROGRAM OF INSPECTION OF DAMS

Name of Dam: BRISTOL FISH AND GAME CLUB DAM
Inventory Number: CT 00299
State: CONNECTICUT
County: NEW HAVEN
Town: WOLCOTT
Stream: CUSSGUTTER
Owner: BRISTOL FISH AND GAME CLUB
Date of Inspection: APRIL 29, 1981
Inspection Team: PETER M. HEYEN, P.E.
MURALI ATLURU, P.E.
JAY A. COSTELLO

Accession For
NTIS GRANT
DTIC TAB
Unannounced
Justification:

By
Distribution/
Availability Codes

Dist Avail and/or
Special

A/1

Bristol Fish and Game Club Dam is located on Cussgutter Brook (Quinnipiac River Basin) in a rural area in the Town of Wolcott, County of New Haven, State of Connecticut. The dam is shown on the Bristol USGS Quadrangle Map, having coordinates latitude N41°37.5' and longitude W72 56.0'. The drainage area is approximately 0.2 square miles and the maximum impoundment to the top of the dam is 130 acre-feet. Elevations given below are not NGVD, but correspond to elevations given on existing plans.

As shown on Sheet B-1, the dam is an earth embankment founded on bedrock and measuring approximately 600 feet long, 22.5 feet high (26.5 structural height), and 12 feet wide at the top. The elevation at the top of the dam is 738.5, which is 4.5 feet above the principal spillway crest. A 5 foot wide by 16 foot high bentonite clay core extends for the length of the dam. This core is placed on the bedrock foundation (elevation 712.0) and rises to elevation 728.0 along the upstream side of the cutoff trench. The upstream slope of the dam is inclined at 3 horizontal to 1 vertical and the downstream slope is inclined at 2 horizontal to 1 vertical. The slopes and top of the embankment have a grass cover, with some riprap along the waterline.

The principal spillway is a concrete drop inlet located on the upstream slope approximately 225 feet from the left end of the dam. This inlet consists of a 4 foot by 1.5 foot (I.D.) concrete riser and a 16 inch reinforced concrete outlet pipe, extending from the riser to the toe of the embankment. The riser has a crest elevation of 734.0, a bottom elevation of 720.3 and the pipe outlets at invert elevation 716.8. There are two vertical 4 foot by 1 foot openings at the top of the riser structure, which allow water to flow into the chamber and out the 16 inch RCP. The low-level outlet, also part of this spillway structure, consists of a 15 inch ACCMP which

extends 20 feet from the riser chamber to the toe of the upstream slope, at invert elevation 121.0. A 14 inch low-level intake valve is located just upstream of the concrete riser, and can be operated with the stem which extends to the riser hood, along the downstream side of the riser chamber.

The emergency spillway is a grass lined channel extending around the right end of the dam. The channel measures approximately 20 feet wide, with side slopes of 3 horizontal to 1 vertical and a crest elevation of 735.0. A small earth dike, measuring about 3 feet high by 80 long, extends along the left side of the spillway.

Based upon the visual inspection performed April 29, 1981, the project is assessed as being in good condition. The following features which could influence the future condition and/or stability of the dam were identified.

1. If the seepage at the toe of the dam is coming through the embankment, it could begin to carry material from the interior of the dam, creating a piping situation and thereby threatening the safety of the structure.
2. The lack of proper riprap protection on the upstream slope will lead to further sloughing and erosion of this slope, which may provide an area for overtopping during flood conditions.
3. Spalling of the concrete at the upstream and downstream sides of the riser hood at the drop inlet openings (Photo 3), could lead to failure of the hood or riser structure, possibly blocking the spillway during periods of high flows.
4. Animal burrows can provide seepage paths through the impervious core, which can promote piping and possibly lead to failure of the dam.

It is recommended that the owner retain a registered professional engineer qualified in dam design and inspection to perform services pertaining to the following items. The engineer should establish recommended corrective procedures which should then be promptly implemented by the owner.

1. Monitoring and evaluation of seepage at the toe of the embankment to determine its origin, affect on the safety of the structure, and any necessary corrective action.

2. Regrading of the upstream slope and placement of sufficient riprap to protect against erosion and sloughing of this slope by wave action. This riprap should be placed between expected high and low water elevations, and should extend around the right end of the embankment to protect against erosion should the emergency spillway be activated.
3. Repairing spalled concrete at the sides of the riser structure hood, along the waterline where water enters the drop inlet.
4. Removing trees to a distance of 10 feet from the toe of the dam with proper backfilling and replacement of protective cover.
5. Elimination of burrowing animals in the embankment, backfilling the burrows and replacement of protective cover.

Also, the owner should initiate a formal program of operation and maintenance procedures, including a monthly inspection by the owner or owner representative and proper documentation to provide accurate records for future reference. A comprehensive program of inspection by a registered professional engineer qualified in dam design and inspection should be instituted on a biennial basis.



OVERVIEW PHOTO
(April, 1981)

US ARMY ENGINEER DIV. NEW ENGLAND CORPS OF ENGINEERS WALTHAM, MASS.	NATIONAL PROGRAM OF INSPECTION OF NON-FED DAMS		Bristol Fish & Game Club Dam Cussgutter Brook	Wolcott CONNECTICUT	DATE June 1981 CE # 27785KH PAGE ix
CAHN ENGINEERS INC. WALLINGFORD, CONN. ENGINEER					

VISUAL INSPECTION CHECK LIST

PARTY ORGANIZATION

PROJECT Eristol Fish & Game Club Dam **DATE:** April 29, 1991

TIME: 12:30 PM - 2:30 PM

WEATHER: Cloudy, 70°F

W.S. ELEV. 734.2 **U.S.** 1/4 **DN.S**

<u>PARTY:</u>	<u>INITIALS:</u>	<u>DISCIPLINE:</u>
1. <u>Peter M. Heynen</u>	<u>PMH</u>	<u>Corn - Geotechnical</u>
2. <u>Murali Atluru</u>	<u>MA</u>	<u>DTC - H/H</u>
3. <u>Jay A. Castello</u>	<u>JAC</u>	<u>Corn - Geotechnical</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____

<u>PROJECT FEATURE</u>	<u>INSPECTED BY</u>	<u>REMARKS</u>
1. <u>Embarkment</u>	<u>PMH, JAC, MA</u>	<u>A-2</u>
2. <u>Principal Spillway (Drop Inlet)</u>	<u>PMH, JAC, MA</u>	<u>A-3</u>
3. <u>Auxiliary Spillway</u>	<u>PMH, JAC, MA</u>	<u>A-4</u>
4. <u>Outlet Structure and Channel</u>	<u>PMH, JAC, MA</u>	<u>A-5</u>
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____
11. _____	_____	_____
12. _____	_____	_____

PERIODIC INSPECTION CHECK LIST

Page 4-2

PROJECT Griffiths Ferry Game Club Dam

DATE Apr 29 1982

PROJECT FEATURE Earth Embankment BY DAVID J. MA

AREA EVALUATED	CONDITION
<u>DAM EMBANKMENT</u>	
Crest Elevation	738.5
Current Pool Elevation	734.2
Maximum Impoundment to Date	Unknown
Surface Cracks	None Observed - Two original curious cracks on crest
Pavement Condition	N/A
Movement or Settlement of Crest	None Observed
Lateral Movement	
Vertical Alignment	Appears Good
Horizontal Alignment	
Condition at Abutment and at Concrete Structures	Good
Indications of Movement of Structural Items on Slopes	None
Trespassing on Slopes	4/s slope at riser structure
Sloughing or Erosion of Slopes or Abutments	Sloughing along waterline and 4/s slope at riser structure
Rock Slope Protection-Riprap Failures	Insufficient riprap at waterline
Unusual Movement or Cracking at or Near Toes	None Observed
Unusual Embankment or Downstream Seepage	Seepage less than 5 gpm; 20' left of outlet and 25' d/s of outlet
Piping or Boils	
Foundation Drainage Features	None Observed
Toe Drains	
Instrumentation System	

PERIODIC INSPECTION CHECK LIST

Page 1

PROJECT Bristol Fish & Game Dock

DATE Apr 2002

PROJECT FEATURE Drop Inlet Riser Structure

BY PM - JAC

AREA EVALUATED	CONDITION
<u>OUTLET WORKS-CONTROL TOWER</u>	Concrete riser structure, crest elevation = 7.24.0
a) <u>Concrete and Structural</u>	
General Condition	Fair
Condition of Joints	Good
Spalling	At each end near waterline - aggregate visible
Visible Reinforcing	None Observed
Rusting or Staining of Concrete	
Any Seepage or Efflorescence	
Joint Alignment	Appears Good
Unusual Seepage or Leaks in Gate Chamber	Not Observed
Cracks	None observed
Rusting or Corrosion of Steel	Rusting of trash rack bar
b) <u>Mechanical and Electrical</u>	
Air Vents	N/A
Float Wells	
Crane Hoist	
Elevator	
Hydraulic System	30 foot long, 15 inch ACCMP intake with 14 inch valve enters u/s side of riser chamber at this base. Outlets by 16 inch RCP at d/s side of riser chamber.
Service Gates	
Emergency Gates	
Lightning Protection System	N/A
Emergency Power System	
Wiring and Lighting System	

PERIODIC INSPECTION CHECK LIST

Page 1

PROJECT Gravel Fish & Game Dam

DATE April 24, 1988

PROJECT FEATURE Anybody's

BY SMS J. A. M.

AREA EVALUATED	CONDITION
<u>OUTLET WORKS-SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS</u>	Gross lined earth channel @ right end of dam
a) <u>Approach Channel</u>	
General Condition	Good
Loose Rock Overhanging Channel	None
Trees Overhanging Channel	
Floor of Approach Channel	Flat- free of debris
b) <u>Weir and Training Walls</u>	
General Condition of Concrete	N/A- earth channel
Rust or Staining	
Spalling	
Any Visible Reinforcing	
Any Seepage or Efflorescence	
Drain Holes	grass cover - good condition, side slopes - good
c) <u>Discharge Channel</u>	earth dike left side - good
General Condition	no riprap at right end dam embankment
Loose Rock Overhanging Channel	channel discharges to woods at right end of dam. Discharge then flows to outlet channel.
Trees Overhanging Channel	
Floor of Channel	
Other Obstructions	

PERIODIC INSPECTION CHECK LIST

Page A-5

PROJECT Bristol Fish & Game Club Dam

DATE Apr 21 1988

PROJECT FEATURE 16" RCP Outlet

BY PRH, FA, VL

AREA EVALUATED	CONDITION
<u>OUTLET WORKS-OUTLET STRUCTURE AND OUTLET CHANNEL</u>	
General Condition of Concrete	16" RCP from riser chamber to d/s toe of embankment (71±')
Rust or Staining	Pipe appears in good condition. Hard to observe
Spalling	N/A
Erosion or Cavitation	
Visible Reinforcing	
Any Seepage or Efflorescence	
Condition at Joints	Could not be observed
Drain Holes	N/A
Channel	
Loose Rock or Trees Overhanging Channel	Some small trees
Condition of Discharge Channel	Narrow, natural stream bed. fair condition

PLATE 1

1. THIS DRAWING WAS DERIVED FROM EXISTING PLANS SUBMITTED BY THE U.S. DEPARTMENT OF AGRICULTURE, SOIL CONSERVATION SERVICE, OFFICE OF THE DISTRICT ENGINEER, WASHINGTON, D.C. (PROJECT NO. 100) AND SUPPLEMENTAL DATA OBTAINED DURING CANAL ENGINEERS INSPECTION ON APRIL 29, 1961.
2. NO M.S.V.D. ELEVATIONS ARE AVAILABLE FOR THE CANAL. THE ELEVATIONS IN THIS DRAWING CORRESPOND TO ELEVATIONS USED ON THE EXISTING DESIGN DRAWINGS. NO CONVERSION TO M.S.V.D. IS KNOWN.

OUTLET EL. 710.8

CANN ENGINEERS INC. WILMINGTON, CONNECTICUT ENGINEER	U.S. ARMY ENGINEER DIVISION CORPS OF ENGINEERS WALTHAM, MASS.
NATIONAL PROGRAM OF INSPECTION OF NON-FED. CANALS PLAN, ELEVATION & SECTION	
WATERWAY AND GAME CLUB	
DESIGNED BY: [REDACTED]	
CHECKED BY: [REDACTED]	
DATE: [REDACTED]	

3 of 3

13

Copy available to DTIC does not permit fully legible reproduction



Photo 1 - Upstream slope from left abutment. Minor sloughing of the upstream slope is occurring at the waterline. Drop inlet can be seen at center of dam (April, 1981).



Photo 2 - Top of dam and downstream slope from left abutment (April, 1981).

US ARMY ENGINEER DIV. NEW ENGLAND
CORPS OF ENGINEERS
WALTHAM, MASS.

CAHN ENGINEERS INC.
WALLINGFORD, CONN.
ENGINEER

NATIONAL PROGRAM OF
INSPECTION OF
NON-FED. DAMS

BRISTOL FISH & GAME CLUB
CUSSGUTTER BROOK
WOLCOTT, CT
CE# 27785 KH
DATE JUNE 1981 PAGE C-1



Photo 3 - Top of concrete riser structure. Casing for low-level outlet valve stem is located on upstream side of riser (April, 1981).



Photo 4 - Emergency spillway at right end of dam (April, 1981).

US ARMY ENGINEER DIV. NEW ENGLAND
CORPS OF ENGINEERS
WALTHAM, MASS.

CAHN ENGINEERS INC.
WALLINGFORD, CONN.
ENGINEER

NATIONAL PROGRAM OF
INSPECTION OF
NON-FED. DAMS

BRISTOL FISHER GAME CLUB
CUSSGUTTER BROOK
WOLCOTT, CT
CE# 27785 KH
DATE JUNE '81 PAGE C-2



Photo 5 - 16 inch RCP which discharges flows from the concrete riser chamber. These flows may be from the drop inlet or from the low-level intake (April, 1981).



Photo 6 - Close-up of riser structure and spalling of concrete at waterline (April, 1981).

US ARMY ENGINEER DIV. NEW ENGLAND
CORPS OF ENGINEERS
WALTHAM, MASS.

CAHN ENGINEERS INC.
WALLINGFORD, CONN.
ENGINEER

NATIONAL PROGRAM OF
INSPECTION OF
NON-FED. DAMS

BRISTOL FISH & GAME CLUB
CUNNINGHAM BROOK
WOLCOTT, CT.
CE# 27785KH
DATE JUNE '81 PAGE C-3



Photo 7 - Erosion and sloughing of upstream slope near drop inlet. Note sparse riprap at waterline (April, 1981).






Photo 8 - Seepage at right side of outlet discharge channel. Seepage flows from wet area at toe of embankment to the right of the outlet pipe (April, 1981).

US ARMY ENGINEER DIV. NEW ENGLAND
CORPS OF ENGINEERS
WALTHAM, MASS.

CAHN ENGINEERS INC.
WALLINGFORD, CONN.
ENGINEER

NATIONAL PROGRAM OF
INSPECTION OF
NON-FED. DAMS

BRISTOL FISH & GAME CLUB
CUSSEGUTTER BROOK
WOLCOTT, CT.
CE# 87705KH
DATE JUNE '81 PAGE C-4



CONTOUR INTERVAL 10 FEET
DATUM IS MEAN SEA LEVEL

BRISTOL QUAD

PROJECT NON FEDERAL DAM INSPECTION PROJECT NO. 81-20-11 SHEET 1 OF 20
NEW ENGLAND DIVISION COMPUTED BY J. A. [unclear] DATE 10/1/81
BRISTOL FISH AND GAME CLUB DAM CHECKED BY E. Butcher [unclear] DATE 5/1/82

PERFORMANCE AT PEAK FLOOD CONDITIONSPROBABLE MAXIMUM FLOOD (PMF) DETERMINATION-

DRAINAGE AREA - 0.18 SQ. MI. PLANIMETERED FROM
BRISTOL QUAD. SHEET (REV. 1972)

WATERSHED CLASSIFICATION - "ROLLING" TO "MOUNTAINOUS"
BASED UPON USGS MAP AND SITE VISIT.

PMF PEAK INFLOW-

FOR SMALL DRAINAGE AREAS (< 2 SQ. MI.) THE CORPS
OF ENGINEERS RECOMMENDS CSM VALUES TO BE NOT
GREATER THAN 2500 CFS/SQ. MI. FOR THE ABOVE
WATERSHED CONDITIONS.

PEAK FLOW RATE SELECTED = 2500 CFS/SQ. MI.

\therefore PMF PEAK INFLOW = $2500 \times 0.18 = 450$ CFS

SIZE CLASSIFICATION-

FOR THE PURPOSE OF DETERMINING PROJECT SIZE, THE
MAXIMUM STORAGE ELEVATION IS CONSIDERED EQUAL TO
THE STORAGE AT TOP OF DAM

TOP OF DAM ELEV. = 865.5 *

TOE OF DAM ELEV. = 843.0

HEIGHT OF DAM 22.5 FT

* The normal W.S. elevation of the Pond is not indicated on
the USGS map. However, examining the contours on
the USGS map as well as elevations given in the
1958 design drawings prepared by SCS, the
normal pond elevation is Assumed to be 861 NAVD
and is assumed to be the same for the Principal
Spillway crest. All other elevations are referenced to this
assumed elevation and are obtained from the 1958
SCS drawings. Cohn Inc. field checked some of the
Key Information

DIVERSIFIED TECHNOLOGIES CORP.

CONSULTING ENGINEERS
NORTH HAVEN, CONN.

PROJECT NON FEDERAL DAM INSPECTION PROJECT NO. 81-20-11 SHEET 2 OF 25
NEW ENGLAND DIVISION COMPUTED BY [Signature] DATE 2/15/41
BRISTOL FISH AND GAME CLUB DAM CHECKED BY E. Butcher B. In DATE 5/1/41

PLANIMETERING FROM USGS MAP FOR POND SURFACE AREAS —
 AT EL. 861 (PR. SPILLWAY CREST) = 12 ACRES
 AT EL. 870 = 15 ACRES
 AT EL. 880 = 21 ACRES

A STAGE-POND AREA CURVE IS PLOTTED (SHEET 3)
 FROM THIS CURVE, POND AREA AT TOP OF DAM = 13.4 AC.
 AVERAGE POND AREA BETWEEN PR. SPILLWAY
 CREST AND TOP OF DAM = 12.7 AC.
 \therefore STORAGE BETWEEN PRINCIPAL SPILLWAY CREST
 AND TOP OF DAM = $4.5 \times 12.7 \approx 57$ AC. FT.
 STORAGE BETWEEN PRINCIPAL SPILLWAY
 CREST AND POND AT EL. 870 = 121.5 AC. FT.
 EST. STORAGE BELOW PR. SPILLWAY CREST = $\frac{1}{3}bh$
 $= \frac{1}{3} \times 12 \times 18 = 72$ AC. FT.


($b = 12$, $h = EL. 861 - EL. 843 = 18'$)

\therefore MAXIMUM IMPOUNDMENT TO TOP OF DAM = $57 + 72$
 $= 129$ AC. FT.

A STAGE-STORAGE CURVE IS PLOTTED ON SHEET 3
 THUS, ACCORDING TO CORPS OF ENGINEERS GUIDE
 LINES TABLE 1, THE BRISTOL CLUB DAM IS
 CLASSIFIED SMALL BASED UPON THE STORAGE
 CAPACITY OF 129 AC. FT. (< 1000 AND ≥ 50)
 AND THE HEIGHT OF THE DAM IS ONLY
 22.5 FT.

D. A. B. 5/15/81

E. Butcher B. B. 5/15/81



STORAGE ABOVE SPILLWAY CREST - AC FT

PROJECT NON FEDERAL DAM INSPECTION PROJECT NO. 81-20-11 SHEET 4 OF 20
NEW ENGLAND DIVISION COMPUTED BY Wm. J. Dwyer DATE 5/15/77
BRISTOL FISH AND GAME CLUB DAM CHECKED BY E. Butler B. Jr. DATE 5/16/77

HAZARD POTENTIAL - LOW

HAZARD POTENTIAL
BASED UPON DAM BREACH ANALYSIS AND ACTIVITIES
BELOW THE DAM. A DETAILED DISCUSSION OF
HAZARD POTENTIAL IS INCLUDED AT THE END
OF BREACH ANALYSIS SECTION OF APPENDIX D.

SELECTION OF TEST FLOOD -

FOR THE SMALL SIZE AND LOW HAZARD
POTENTIAL CLASSIFICATION, TABLE 3 OF CORPS
OF ENGINEERS RECOMMENDED GUIDELINES, THE
TEST FLOOD COULD BE IN THE 50 YEAR
TO 100 YEAR FREQUENCY RANGE.

BASED UPON THE INVOLVED RISK POTENTIAL
DOWNSTREAM OF THE DAM, A TEST FLOOD
= 100 YR IS SELECTED.

$$\therefore \text{TEST FLOOD PEAK INFLOW} = \frac{5}{19} \times 450 \\ \approx \underline{120 \text{ CFS.}}$$

NOTE: PMF OF 450 CFS IS ESTIMATED TO RESULT
FROM 19" RUN-OFF AND A 100 YEAR
FLOOD IN CONNECTICUT IS ESTIMATED TO
RESULT FROM APPROXIMATELY 5" RUN-OFF.

PROJECT NON FEDERAL DAM INSPECTION

PROJECT NO. 81-20-11 SHEET 5 OF 20


NEW ENGLAND DIVISION

COMPUTED BY John A. Dwyer DATE 5/15/81

BRISTOL FISH AND GAME CLUB DAM

CHECKED BY E. J. Tuller DATE 5/16/81

COMPOSITE DISCHARGE RATING CURVE



APPROXIMATE POTENTIAL OVERFLOW PROFILE

BASED ON DESIGN DRAWINGS & CAHN INC'S FIELD INFORMATION

(LOOKING DOWNSTREAM)

DAM

$$Q_1 = CLH^{3/2} \\ = 1624 H^{3/2}$$


$C = 2.8$ ASSUMED (Earth) $L = 580'$, $CY EL = 865.5$

EMERGENCY SPILLWAY

$$Q_2^0 = CLH^{3/2} \\ = 56 H^{3/2}$$

$C = 2.8$ ASSUMED (Grass) $L = 20'$, $CY EL = 862.0$

$$Q_2' = \frac{2}{5} \frac{CL}{(h_b - h_a)^{5/2}} (h_b^{5/2} - h_a^{5/2}) * \\ = 0.4 \times 2.8 \times 3 \times h_b^{5/2} \text{ up to EL. 865.5} \\ = 3.36 h_b^{5/2}$$



$$\text{SIMILARLY } Q_2'' = 3.36 h_b^{5/2} \\ \therefore Q_2' + Q_2'' = 6.72 h_b^{5/2}$$

*NOTE: USGS RECOMMENDED FORMULA FOR MORE PRECISE DISCHARGE OVER INCLINED DAM/EMBANKMENT CREST (REF: MEASUREMENT OF PEAK DISCHARGES AT DAM BY INDIRECT METHODS. USGS BOOK 3, CHAPTER A 5, PAGE 3-4, 1968)

PROJECT NON FEDERAL DAM INSPECTION PROJECT NO. 81-20-11 SHEET 6 OF 20
NEW ENGLAND DIVISION COMPUTED BY [Signature] DATE 5/15/81
BRISTOL FISH AND GAME CLUB DAM CHECKED BY [Signature] DATE 5/16/81

PRINCIPAL SPILLWAY:

PIPE SPILLWAY WITH DROF INLET

$$Q_{ps} = a \sqrt{\frac{2gH}{1 + K_e + K_b + K_f L}}$$

(Ref: "Hand Book of Applied Hydrology" by Ven Te Chow
P - 21-63)

FOR CONCRETE PIPE

Pipe diameter = 16"

$n = 0.015$, $K_e = 0.5$


Area of cross section of pipe

$K_b = 0$, $K_f = 0.0201$, $L = 72.5'$

= 1.37 sq. ft.

FOR FULL FLOW CONDITION

$$Q = 5.91 H^{1/2}$$



LOW LEVEL OUTLET

$$Q_o = CA \sqrt{2gH}$$

$$= 8.51 H^{1/2}$$

= 250 CFS FOR POOL
AT TOP OF DAM

14" PIPE


... - 849.6 (CL)
EI 849

THE LOW LEVEL OUTLET IS PART OF THE PRINCIPAL SPILLWAY STRUCTURE AND ITS EFFECT ON THE DISCHARGE CAPACITY OF THE SPILLWAY IS NEGLECTED. THE FLOW THROUGH THE LOW LEVEL OUTLET IS CONSIDERED INCONSEQUENTIAL IN THIS ANALYSIS, WHILE THE PRINCIPAL SPILLWAY IS OPERATING.

TABULATION OF DISCHARGE RATES (CFS)

ELVN NGVD	DAM Q_1	EMER. SPILLWAY Q_2	$Q_2' + Q_2''$	Q_2	PRINCIPAL SP. WAY Q_{ps}	TOTAL Q
PR. SPILL 861	0	0	0	0	0	0
862	0	0	0	0	6	6
TEST FLOW 862.95	0	45	5	50	8	58
863	0	56	7	63	9	72
864	0	158	38	196	10	206

And. Dr. 2/12/81
 E. Butlin Baln 5/16/81



PROJECT NON FEDERAL DAM INSPECTION PROJECT NO. 81-20-11 SHEET 8 OF 20
NEW ENGLAND DIVISION COMPUTED BY Dan Sir DATE 5/15/81
BRISTOL FISH AND GAME CLUB DAM CHECKED BY E. Butcher DATE 5/16/81

DETERMINATION OF PEAK OUTFLOW -

SHORTCUT ROUTING OF POND

CORPS OF ENGINEERS GUIDELINES SURCHARGE STORAGE

ROUTING ALTERNATIVE METHOD USED

FOR 120 CFS (100 YR) THE DISCHARGE RATING CURVE
GIVES ELVN = 863.5

AND FROM STAGE-STORAGE CURVE FOR THIS ELVN
STORAGE = 31 AC.FT.

$$\text{STOR}_i = \frac{31 \times 12}{0.18 \times 640} = 3.23'' \text{ RUN-OFF.}$$

$$Q_{P_i} = Q_{P_i} \left(1 - \frac{\text{STOR}_i}{5} \right)$$

① STOR _i INCHES	② $\left(1 - \frac{\text{STOR}_i}{5} \right)$	③ STOR _i AC.FT $\frac{0.18 \times 640}{12}$	④ Q _{P_i} CFS ① × 120	⑤ ELVN FROM STORAGE CURVE USING ②
2.5	0.5	24	60	862.25
3.00	0.4	29	48	863.25
3.23	0.35	31	42	863.5

COLUMNS ④ & ⑤ ARE PLOTTED ON DISCHARGE RATING
CURVE AND

PEAK OUTFLOW Q = 58 CFS

MAXIMUM STAGE = 862.85 NGVD

TOP OF DAM = 865.5 NGVD

∴ THE DAM IS NOT OVERTOPPED.

PROJECT NON FEDERAL DAM INSPECTIONPROJECT NO. 81-20-11SHEET 9 OF 20

NEW ENGLAND DIVISION

COMPUTED BY Wm J. Jr.DATE 2/14/81

BRISTOL FISH AND GAME CLUB DAM

CHECKED BY E. ButcherDATE 5/15/81BREACH ANALYSIS - DOWNSTREAM FAILURE HAZARD

BASED UPON CORPS OF ENGINEERS "RULE OF THUMB"
GUIDANCE FOR ESTIMATING DIS DAM FAILURE
HYDROGRAPHS

$$\text{BREACH OUTFLOW } Q_b = \frac{8}{27} \times W_b \times \sqrt{g} \times Y_0^{3/2}$$

HEIGHT FROM CHANNEL BED TO POOL @ TOP OF DAM Y_0
= 22.5 FT.

ESTIMATED BREACH WIDTH W_b = 40% OF MID-HT LENGTH
OF DAM = $0.4 \times 265 = 106$ FT

(MID HEIGHT LENGTH IS BASED UPON SES DESIGN DRAWINGS)

$$\therefore Q_b = \frac{8}{27} \times 106 \times \sqrt{32.2} \times (22.5)^{3/2} \approx 19,020 \text{ CFS}$$

IT IS PRESUMED THAT THE BREACH OCCURS IN DEEPEST
SECTION OF THE DAM. THIS SECTION INCLUDES THE
PRINCIPAL SPILLWAY AS WELL AS THE LOW LEVEL OUTLET.
THE ESTIMATED DISCHARGE THROUGH EMERGENCY
SPILLWAY WITH POOL AT TOP OF THE DAM = 521 CFS

$$\therefore \text{PEAK FAILURE OUTFLOW } Q_p = 19,020 + 521 \approx 19,600 \text{ CFS}$$

ESTIMATED FAILURE FLOOD DEPTH $\approx 0.44 Y_0$
IMMEDIATELY D/S FROM DAM $\approx 10 \text{ FT}$

DIVERSIFIED TECHNOLOGIES CORP.

CONSULTING ENGINEERS
NORTH HAVEN, CONN.

PROJECT NON FEDERAL DAM INSPECTION PROJECT NO. 81-20-11 SHEET 10 OF 20
NEW ENGLAND DIVISION COMPUTED BY Don. H. DATE 5/15/81
BRISTOL FISH AND GAME CLUB DAM CHECKED BY E. Butcher DATE 5/15/81

PERFORM DIS ROUTING OF PEAK FAILURE OUTFLOW
SECTION AA IS SELECTED AT 1000 FT DIS OF DAM

$Q = \frac{1.486}{n} \times A \times R^{2/3} \times S^{1/2}$ Where $n = 0.06$ assumed (stones, windy)
 and $S = 0.043$ Est. from USGS map.
 $= 5.136 A R^{2/3}$
 A AND R ARE ESTIMATED BASED UPON USGS MAP INFORM.

ELVN	A sq. ft	P	R	$R^{2/3}$	Q - CFS
800	0	-	-	-	0
802	38	38.2	0.995	0.997	195
805	237.5	95.5	2.49	1.838	2242
808	614	154.3	3.98	2.513	7925
810	950	191	4.97	2.914	14,218
811	1151	213.1	5.40	3.08	18,208
812	1372	233	5.9	3.3	23,255

FROM STAGE-AREA AND STAGE DISCHARGE CURVES
 FOR $Q_{P1} = 19,600$ CFS, ELVN = 811.25, AREA = 1206 sq ft
 VOLUME OF REACH $V_1 = \frac{1000 \times 1206}{43.560} \approx 28$ AC. FT.
 TRIAL $Q_{P2} = Q_{P1} \left(1 - \frac{V_1}{S}\right) = 19,600 \left(1 - \frac{28}{129}\right) = 15,350$ CFS
 FOR THIS Q_{P2} THE STAGE-DISCHARGE CURVE GIVES ELVN = 810.25

AND AREA = 998 sq. ft.

VOLUME OF REACH $V_2 = \frac{1000 \times 998}{43.560} \approx 23$ AC. FT.
 RECOMPUTING $Q_{P2} = 19,600 \left(1 - \frac{28.723}{129}\right) = 15,725$ CFS

PEAK OUTFLOW $Q_{P2} = 15,725$ CFS

FLOOD STAGE AT SECTION AA = 810.4 NGVD

FLOOD DEPTH AT SECTION AA = 810.4 - 800 = 10.4 FT


VELOCITY AT SECTION AA = $\frac{15,725}{1028} \approx 15$ FPS

SHEET 11 OF 20

Amel. dhr 3/14/61

E. Butler B.N. 5/15/61

BRISTOL DAM
STAGE-AREA CURVE
SECTION A-A




D-11

SHEET 12 OF 20

Unit: ft/s 5/14/81

E. Buehler, B. B. 5/15/81

BRISTOL DAM
STAGE-DISCHARGE CURVE



SECTION A

DISCHARGE IN CFS

DIVERSIFIED TECHNOLOGIES CORP.

CONSULTING ENGINEERS
NORTH HAVEN, CONN.

PROJECT NON FEDERAL DAM INSPECTION PROJECT NO. 81-20-11 SHEET 13 OF 20
NEW ENGLAND DIVISION COMPUTED BY [Signature] DATE 5/15/71
BRISTOL FISH AND GAME CLUB DAM CHECKED BY E. B. [Signature] DATE 5/15/71

SELECTING A SECTION BB 900' DIS OF SECTION AA

$$Q = \frac{1.486}{n} \times A \times R^{2/3} \times S^{1/2} \quad \text{Where } n = 0.06 \text{ assumed}$$

$$= 6.553 A R^{2/3} \quad A = 0.07 \text{ based on USGS map}$$

ELVN	A	P	R	R ^{2/3}	Q
730	0	—	—	—	0
734	185	92.95	1.992	1.584	1920
736	418.5	140.02	2.989	2.076	5693
738	740	185.7	3.985	2.515	12,196
740	1150	230.9	4.991	2.918	21,990

STAGE AREA AND STAGE DISCHARGE CURVES ARE PLOTTED -
FOR $Q_{P1} = 15,725$ CFS, ELVN = 738.8, AND AREA = 898 SQ. FT.

$$\text{VOLUME OF REACH } V_1 = \frac{900 \times 898}{43.560} \approx 18.5 \text{ AC. FT}$$

$$\text{TRIAL } Q_{P2} = Q_{P1} \left(1 - \frac{V_1}{S}\right) = 15,725 \left(1 - \frac{18.5}{129}\right) = 13,470 \text{ CFS}$$

FOR 13,470 CFS, ELVN = 738.35 AND AREA = 810 SQ. FT.

$$\text{VOLUME OF REACH } V_2 = \frac{900 \times 810}{43.560} \approx 16.75 \text{ AC. FT}$$

$$\text{RECOMPUTING } Q_{P2} = 15,725 \left(1 - \frac{18.5 + 16.75}{2 \times 129}\right) \approx 13,575 \text{ CFS}$$

$$\text{PEAK OUTFLOW } Q_{P2} = 13,575 \text{ CFS}$$

$$\text{FLOOD STAGE AT SECTION BB} = 738.4 \text{ NGVD}$$


$$\text{FLOOD DEPTH AT SECTION BB} = 738.4 - 730 = 8.4 \text{ FT}$$

$$\text{VELOCITY AT SECTION BB} = \frac{13,575}{819} \approx 16.5 \text{ FPS}$$

SHEET 14 OF 20

Am. 16 5/11/81

E. Butler Barre 5/15/81




SHEET 15 OF 20

Amel. Rbr 5/19/21

E Buttila Bdr 5/15/21

BRISTOL CLUB DAM
STAGE-DISCHARGE CURVE



D-15

PROJECT NON FEDERAL DAM INSPECTION PROJECT NO. 81-20-11 SHEET 16 OF 20
NEW ENGLAND DIVISION COMPUTED BY [Signature] DATE 5/11/71
BRISTOL FISH AND GAME CLUB DAM CHECKED BY [Signature] DATE 5/15/71

SELECT A SECTION CC 3700' D/S OF SECTION BB

A CONSIDERABLE REACH LENGTH (3300'±) BELOW SECTION BB IS EXTREMELY STEEP AND NARROW. THEREFORE, ATTENUATION OF STORAGE VOLUME IS CONSIDERED NEGLIGIBLE. THE REACH LENGTH USED IN THIS ANALYSIS IS THEREFORE 400'.

$$Q = \frac{1.486}{n} \times A \times R^{2/3} \times A^{1/2}$$

$$= \underline{6.443} A R^{2/3}$$

Where $n = 0.05$ assumed
 $\lambda = 0.047$ Est. from
 USGS map.

ELVN	A SQ. FT	P	R	$R^{2/3}$	Q CFS
230	0	—	—	—	—
232	210	210	1	1	1350
234	820	410	2	1.59	8400
235	1312	525	2.5	1.84	15,555

STAGE AREA AND STAGE DISCHARGE CURVES ARE PLOTTED
 FOR $Q_{P_1} = 13,575$ CFS, ELVN = 234.75 & AREA = 1188 SQ. FT.
 VOLUME OF REACH $V_1 = \frac{400 \times 1188}{43.560} \approx 11$ AC. FT

TRIAL $Q_{P_2} = Q_{P_1} \left(1 - \frac{V_1}{S}\right) = 13,575 \left(1 - \frac{11}{129}\right) \approx 12,400$ CFS
 FOR 12,400 CFS, ELVN = 234.6 & AREA = 1104 SQ. FT.
 ∴ VOLUME OF REACH $V_2 = \frac{400 \times 1104}{43.560} \approx 10$ AC. FT

RECOMPUTING $Q_{P_2} = 13,575 \left(1 - \frac{10}{129}\right) \approx 12,400$ CFS.

PEAK OUTFLOW $Q_{P_2} = 12,400$ CFS

FLOOD STAGE AT SECTION CC = 234.6 NGVD

FLOOD DEPTH AT SECTION CC = 234.6 - 230 = 4.6 FT.

VELOCITY AT SECTION CC = $\frac{12,400}{1104} \approx 11$ FPS

SHEET 17 OF 20

Amul. No. 5114/81


E Butli Bahu 5115/81

BRISTOL CLUB DAM
STAGE AREA CURVE
SECTION CC

ELEVATION IN FEET
230
232
234
236
238
240

700 600 500 400 300 200 100 0

HORIZONTAL DISTANCE IN FEET LOOKING DOWNSTREAM




SHEET 18 OF 20

Am. C. 5/17/81

E Butcher Baln 5/15/81

BRISTOL CLUB DAM
STAGE DISCHARGE CURVE



PROJECT NON FEDERAL DAM INSPECTION

PROJECT NO. 81-20-11 SHEET 19 OF 2

NEW ENGLAND DIVISION

COMPUTED BY

DATE

BRISTOL FISH AND GAME CLUB DAM

CHECKED BY

DATE

FAILURE HAZARD POTENTIAL

BASED UPON THE EXISTING INFORMATION, THE LOWEST SECTION OF THE DAM APPEARS TO BE IN THE VICINITY OF THE PRINCIPAL SPILLWAY WITH LOW LEVEL OUTLET AND HENCE IT IS PRESUMED THAT BREACH OF THE DAM WOULD OCCUR IN THIS VICINITY.

THE FAILURE ANALYSIS WAS PERFORMED WITH POOL AT TOP OF DAM (EL. 865.5 NGVD).

SUMMARY OF BREACH ANALYSIS RESULTS:

LOCATION	DISTANCE FROM DAM, FT	PEAK FLOW RATE, CFS	FLOOD STAGE, NGVD	FLOOD DEPTH, FT	VELOCITY FPS
DAM	0	19,600	853.0	10.0	—
AA	1000	15,725	810.4	10.4	15
BB	1900	13,575	738.4	8.4	16.5
CC	5600	12,400	234.6	4.6	11

A CONSIDERABLE PORTION OF THE CUSCUTTER BROOK DOWNSTREAM OF THE DAM TRAVERSES THROUGH THE BRISTOL FISH AND GAME CLUB PROPERTY AND HUNTING, FISHING AND HIKING ACTIVITIES TAKE PLACE IN THIS REACH. AT DAM BREACH CONDITION, THE FLOOD DEPTHS IN THIS REACH IS ESTIMATED TO BE 10.4 FT (SECTION AA) AND 8.4 FT (SECTION BB) WITH VERY HIGH VELOCITIES (15-16.5 FPS).

FURTHER, DOWNSTREAM, THE BRIDGE ON LAKE AVE. WITH AN OPENING OF 3' X 11' IS LIKELY TO BE IMPACTED WITH HIGH VELOCITY (11 FPS) FLOW OF 12,400 CFS. IN ADDITION, THERE ARE 3 HOUSES ADJACENT TO THE BROOK ON LAKE AVE. WITH 1ST FLOOR ELEVATIONS BETWEEN 7' TO 8.5', WHICH COULD HAVE SOME CELLAR FLOODING.

SINCE, OVERNIGHT CAMPING ON CLUB PROPERTY IS NOT PERMITTED, LOSS OF LIFE FROM DAM FAILURE IS UNLIKELY. HENCE, A HAZARD POTENTIAL OF LOW MAGNITUDE IS CONSIDERED LIKELY.

DIVERSIFIED TECHNOLOGIES CORP.CONSULTING ENGINEERS
NORTH HAVEN, CONN

PROJECT NON FEDERAL DAM INSPECTION PROJECT NO. 81-20-11 SHEET 20 OF 20
NEW ENGLAND DIVISION COMPUTED BY [Signature] DATE 2/1/81
BRISTOL FISH AND GAME CLUB DAM CHECKED BY E. Butler DATE 2/1/81

SUMMARY- HYDRAULIC/HYDROLOGIC COMPUTATIONS**PERFORMANCE AT PEAK FLOOD CONDITIONS**

TEST FLOOD	100 YR
PEAK INFLOW	120 CFS
PEAK OUTFLOW	58 CFS
PRINC. SPILL. CAP. TO TOP OF DAM (EL. 865.5 NGVD)	27 CFS
PRINC. SP. CAP. TO TOP OF DAM % OF PEAK OUTFLOW	47
PRINC. SP. CAP. TO PEAK FLOOD ELVN 862.85 NGVD	8 CFS
PRINC. SP. CAP. TO PEAK FLOOD ELVN % OF PEAK OUTFLOW	14
EMERGENCY SP. CAP. TO PEAK FLOOD ELVN	50 CFS
EMERGENCY SP. CAP. TO PEAK FLOOD EL % OF PEAK OUTFLOW	86

PERFORMANCE:

MAXIMUM POOL ELVN	862.85 NGVD
MAX. SURCHARGE HEIGHT ABOVE PRINC. SP. CREST	1.85 FT
NON-OVERFLOW SECTION OF THE DAM OVERTOPPED	NO

DOWNSTREAM FAILURE CONDITIONS

PEAK FAILURE OUTFLOW	19,600 CFS
FLOOD DEPTH IMMEDIATELY D/S FROM DAM	10 FT
CONDITIONS AT THE IMPACT AREA: SECTION CC (LAKE AVE) (STREAM BED EL. 230)	
EST. STAGE BEFORE FAILURE	230.4 NGVD
EST. STAGE AFTER FAILURE WITH 12,400 CFS	234.6 NGVD
EST. RAISE IN STAGE AFTER FAILURE ΔY_1	4.2 FT

END

FILMED

10-84

DTIC